
Federal Communications Commission

**Before the
Federal Communications Commission
Washington, D.C. 20554**

In the Matter of

AAT Communications Corporation
ASR# 1216181
Emmett, Idaho

)
)
)
)
)

File No. EB-04-PO-038

NOV No. V20043292003

NOTICE OF VIOLATION

Released: March 11, 2004

By the Resident Agent, Portland Office, Enforcement Bureau:

1. This is a Notice of Violation ("Notice") issued pursuant to Section 1.89 of the Commission's Rules,¹ to AAT Communications Corporation.

2. On March 8, 2004, the FCC Portland Resident Agent Office received a copy of a Notice to Airmen ("NOTAM") referred from the Federal Aviation Administration in Boise, Idaho. The investigation from this Office revealed that since February 7, 2004, the FAA has issued three consecutive NOTAMs (BOI D 02/023, BOI D 03/009, and BOI D 03/024) to a registered antenna structure located in Little Canyon near Emmett, Idaho due to problems with the antenna structure's lighting equipment. FCC records show that the referenced antenna structure was registered to AAT Communications Corporation, under Antenna Structure Registration Number 1216181. The geographic coordinates for this antenna site are N43-48-38, W116-29-03.

Section 17.56(a) of the Commission's Rules, 47 C.F.R. § 17.56(a), states that "Replacing or repairing of lights, automatic indicators or automatic control or alarm systems shall be accomplished as soon as practicable."

3. In addition, your FCC Antenna Structure Registration for the referenced antenna structure was incorrectly registered. The obstruction marking and lighting, Chapters 4, 8 (M-Dual), and 12, specified by the FAA Aeronautical Study Number 00-ANM-0927-OE, were not included in the FCC Antenna Structure Registration Number 1216181.

Section 17.22 of the Commission's Rules, 47 C.F.R. § 17.22, states that "Whenever painting or lighting is required, the Commission will generally assign specifications in accordance with FAA Advisory Circulars."

4. Pursuant to Section 308(b) of the Communications Act of 1934, as amended,² and

¹ 47 C.F.R. § 1.89.

² 47 U.S.C. § 308(b).

Federal Communications Commission

Section 1.89 of the Commission's Rules, AAT Communications Corporation must submit a written statement concerning this matter within 20 days of release of this Notice. The response must fully explain each violation, must contain a statement of the specific action taken to correct the violations and preclude recurrence, and should include a time line for completion of pending corrective action. The response must be complete in itself and signed by a principal or officer of the licensee with personal knowledge of the matter. All replies and documentation sent in response to this Notice should be marked with the File No. and NOV No. specified above, and mailed to the following address:

Federal Communications Commission
Portland Resident Agent Office
P.O.Box 61469
Vancouver, WA 98666

5. This Notice shall be sent to AAT Communications Corporation, 517 Route One South, Suite 5000, Iselin, NJ 08830.

6. The Privacy Act of 1974³ requires that we advise you that the Commission will use all relevant material information before it, including any information disclosed in your reply, to determine what, if any, enforcement action is required to ensure compliance. Any false statement made knowingly and willfully in reply to this Notice is punishable by fine or imprisonment under Title 18 of the U.S. Code.⁴

FEDERAL COMMUNICATIONS COMMISSION

Binh Nguyen
Resident Agent
Portland Office

³ P.L. 93-579, 5 U.S.C. § 552a(e)(3).

⁴ 18 U.S.C. § 1001 *et seq.*